HAIR DISC BRAKES Auxiliary Lift Axles

- Optimum performance
- More braking power
- Reduced stopping distance





For any questions regarding ADB or your lift axle requirements, call 800.660.2829 or visit www.hendrickson-intl.com

Premium Braking Solution

Hendrickson Auxiliary Axle Systems is now offering air disc brakes on several lift axle configurations on COMPOSILITE® and TOUGHLIFT® product lines for both steer and non-steer applications. Air disc brakes help increase service intervals, lower maintenance and reduce stopping distance with increased braking power.



AIR DISC BRAKES Auxiliary Lift Axle Systems

| TRUCK | | | | | | |
|--------------|------------------|---------------|--------------------|-----------------------|--|--|
| COMPOSILITE® | | | | | | |
| Model | Example Part No. | Application | Capacity (lbs.) | Weight (lbs. est.) | | |
| SCT13 | SCT13CD1X0AXMX | Steerable | 13,500 | 985 | | |
| SCT20 | SCT20CD2X1AHTX | Steerable | 20,000 | 1,450 | | |
| FXT13 | FXT13DED1X1CXMX | Non-Steerable | 13,500 | 1,035 | | |
| TOUGHLIFT® | | | | | | |
| FMT20 | FMT20A43DC0CSPX | Non-Steerable | 20,000 | 1,250 | | |

| TRAILER | | | | | | | |
|--------------|------------------|---------------|--------------------|-----------------------|--|--|--|
| COMPOSILITE® | | | | | | | |
| Model | Example Part No. | Application | Capacity (lbs.) | Weight (lbs. est.) | | | |
| SCW(B)13 | SCB13ID1X0FVMX | Steerable | 13,500 | 976 | | | |
| SCW(B)20 | Available Soon | Steerable | 20,000 | _ | | | |
| FXW13 | Available Soon | Non-Steerable | 13,500 | _ | | | |
| TOUGHLIFT® | | | | | | | |
| FMW(B)22 | Available Soon | Non-Steerable | 22,000 | _ | | | |



All Hendrickson fully dressed air disc brake packages include installation of disc brake calipers, air chambers, lining pads, hub and rotor assemblies, bearings, seals, hub caps and lubricant.

Application Information

- 1. Wheel and Valve Stem Packaging Caution: Great care must be taken in selecting combinations of wheel and valve stem products that are compatible with air disc brakes. Hendrickson Auxiliary Axle System customers will need to review wheel end and valve stem packaging with the manufacturer of the selected air disc brake to confirm adequate running clearances. Hendrickson engineering can assist customers in discussions with the air disc brake manufacturer.
- 2. ABS Sensors Hendrickson fully dressed auxiliary axles require straight ABS sensors. ABS sensing will be via hub-mounted tone rings.
- 3. Air Chamber Selection Air chamber selection is based on the capacity of the auxiliary axle and will default to the proper air chamber in accordance with these requirements.
- 4. Suspension Availability Air disc brake packages are available on most Hendrickson auxiliary axle suspensions. Refer to tables above for current availability.







Available Package Options

Air Disc Packaging* **Bendix ADB22X**

Lining: Jurid 539/BX275

Chamber: ** Varies based on axle specification

Ductile Iron / Aluminum Hub:

Rotor: 430 mm for 22.5- and 24.5-in. tires

- Bendix ADB22X currently available on the above listed models. Multiple other vendors will be available soon.
- ** Some components are determined by model specification, such as axles, brakes, and brake chambers. Contact Hendrickson Specialty Products – Auxiliary Axle Systems with the lift axle model / serial number to determine the axle capacity and chamber requirements.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors. All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at **800.660.2829** or **800.668.5360** in Canada for additional information.



www.hendrickson-intl.com

SPECIALTY PRODUCTS -**AUXILIARY AXLE SYSTEMS** 277 North High Street

Hebron OH 43025 USA 800.660.2829 740.929.5600 • Fax 740.929.5601 Hendrickson Canada ULC

2825 Argentia Road, Unit #2 - 4 Mississauga, ON Canada L5N 8G6 800 668 5360

905.789.1030 • Fax 905.802.9423